

Fearnley Procter



LEVEL 3

FACILITY APPROVAL

Shanghai Hilong Drill Pipe Co. Ltd.

No.1825 Luodong Road, Baoshan Industrial Zone, Shanghai, 200949, P.R.C.

Fearnley Procter certify that the above company's Quality Management System has been assessed and found compliant with

ISO/TS 29001:2010

(Petroleum, Petrochemical and Natural Gas Industries — Sector-specific Quality Management Systems Requirements for Product and Service Supply Organisations)

&

Fearnley Procter NS-1™ Edition 3 Quality and Inspection Requirements for New and Refurbished Drilling and Well Completion Equipment.

SCOPE:

Specifications

Drill Pipe with Welded Tool Joints

NS.03.30.00.1110

Service/Process

1. Heat Treatment, Threading, Inspection and Testing of Tool Joint manufactured from thick wall seamless steel pipe material.
2. Upset, Heat Treatment, Inspection and Testing of Drill Pipe Body.
3. Assembly, Inspection and Testing of Drill Pipe.

CONDITIONS:

1. All processes to be performed at the above facility.
2. Heat treatment, Threading, Inspection and Testing of Tool Joint can also be supplied by Hilong Drill Pipe (Wuxi) Co., Ltd.

EXCLUSIONS:

1. ISO/TS 29001: Section 7.3 Design & Development.

Issued By

A handwritten signature in black ink, appearing to read 'Kevin Fearnley', is written over a light green background.

Kevin Fearnley

Chairman NS-1™ Technical Review Committee

Review No : FP NS 091

Certificate No : 0045/14-3

Approval Date : 15th January, 2014

Valid Till : 14th January, 2016

Registered Since : 15th January, 2009

To maintain validity during the said period the above named Company must fully comply with the current requirements of ISO/TS 29001 and Fearnley Procter NS-1™ Edition 3 Quality and Inspection Requirements for New and Refurbished Drilling and Well Completion Equipment latest revisions. Certificates can be verified at Fearnley Procter Website www.fearnleyproctergroup.com